

31

Monday, 7/9/2007 11:48:17 AM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : LONG STEP ASSEMBLY HIGH SKID RH
 Job Number : 33378
 Estimate Number : 10274
 P.O. Number : N/A Part Number : D350591312
 This Issue : 7/9/2007 S.O. No. : N/A Drawing Number : D3272 REV B
 Prsht Rev. : NC Project Number : N/A
 First Issue : N/A Type : LARGE FAB ASSY Drawing Revision : B
 Previous Run : 31617 Material : N/A
 Due Date : 7/30/2007 Qty: 10 Um: Each
 Written By : John. 07.09
 Checked & Approved By : John. 07.09
 Comment : Est Rev:A 04.03.22 New issue KJ/RF
 Est Rev:B 07-06-09 Added D3572-1 JLM

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description :

1.0 DC DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Photocopy bluefile and type labels as per PPP D350-591-312 CHG001

KS 07.07.24 (10)

2.0 D32721 STEP



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

STEP

BATCH: B 33372

K

PE 01.01.25

3.0 D30671 End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3067-1 End Plate 332836

PE 01.01.25

10

4.0 D32191 Support



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3219-1 Support 331660 = 3333428 = 17

PE 01.07.25 10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:48:17 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 33378

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod M103794
M104721

3-Grind End Plate flush

A.M. 07.08.01

P.E. 07.07.25 10
P.E. 07.07.26 10

(10)

6.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

PD 07.08.01 (10)

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

EP 07/08/01 (Y10LN)

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

A.M. 07.08.01

(10)

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

EP 07/08/16 (X10LN)

10.0

D3065041

Step Leg Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s)

Pick:

Qty Part Number Description Batch

1 D3065-041 Step Leg Assy 332032

A.M. 07.08.21 10

11.0

D30661

Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total: 20.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3066-1 Spacer 333857

A.M. 07.08.21 10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:48:17 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 33378

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

12.0

MS20600AD4W4

Rivets



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

16 MS20600AD4W4

Rivet

M103547

a.m

07.08.21

10

13.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Assemble Leg Assembly as per Dwg D3272.

a.m

07.08.21

10

14.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

7-08-21 (W)

15.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D3067-1

End Plate

B.32836

PL 07.08.21

10

16.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel Aft end for welding

2-Inspect for foreign object as per QSI 024

3-Weld Aft End Plate as per QSI 004 & Dwg D3272

A/R Aluminum Rod

M103794

4-Grind End Plate flush

a.m

07.08.22

10

5-Install last rivet.

a.m

07.08.22

10

PL 07.08.21

10

PL 07.08.21

10

PL 07.08.21

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:48:17 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 33378

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

17.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

07/08/22 (10)

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07/08/20 (10)

19.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Touch up Alodine

BR/M-V 07-08-22

(10)

20.0

POWDER COATING

POWDER COATING1



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

FR/BR

07/08/23

(10)

21.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3272 and QSI 005 4.4

M 104942

(10x)

m-k

07/08/23

22.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: Inspect Powder Coat and Wing Walk

2/24 SP

(10x)

23.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

24.0

D22303

Mounting Lug



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 D2230-3 Mounting Lug

B30993-

07/08/24 (10)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:48:17 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 33378

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

25.0

D2618

Bushing



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2618

Bushing

33991

7/8/24 SP

26.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 6.0000 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2856-400-720 Abrasion Strip

D32992

27.0

D32351

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D3235-1

Mounting Lug

D30996

28.0

D3278041

Support Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D3278-041

Support Assembly

D33430

29.0

AN335A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN3-35A

Bolt

M104021

30.0

AN413A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 AN4-13A

Bolt

M104746

7/8/24 (10)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:48:17 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 33378

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

31.0

AN536A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN5-36A

Bolt

M105057 -

32.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD10

Washer

M104885 -

33.0

AN960JD416

Washer



Comment: Qty.: 16.0000 Each(s)/Unit Total : 160.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

16 AN960JD416

Washer

M104215 -

34.0

AN960JD516

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD516

Washer

M104156 -

35.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L3

Nut (or -3)

M104936 -

EP 7/68/24

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: 1 Date: 07/08/27
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 7/9/2007 11:48:18 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LONG STEP ASSEMBLY HIGH SKID RH

Job Number: 33378

Part Number: D350591312

Job Number:



Seq. #:

Machine Or Operation:

Description :

36.0

MS21042L4

Nut



Comment: Qty.: 8.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

8 MS21042L4 Nut (or -4)

M103914 (8X)

M104248 (62X)

37.0

MS21042L5

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L5 Nut (or -5)

M104547

EP 5/10/08/24 (10)

38.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

1008.24 (10)

39.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-591-312

Location:

Leub

U 57.08.25

10

40.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

10 07/08/27

Job Completion



U 8/08/27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART

DESIGN <i>GP</i>	DRAWN BY <i>B</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>H</i>	DRAWING NO. D3272	REV. B SHEET 1 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	
B	07.05.18	D3272-1 WAS D2622-120	

RELEASED07.06.04 *ff*

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.


SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. **33378**

Copyright © 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART

DESIGN	90	DRAWN BY	10	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED	Le	APPROVED	11	DRAWING NO. D3272
DATE	07.05.18	TITLE	STEP ASSEMBLY, HI LONG	REV. B SHEET 2 OF 3
		SCALE	1:20	



D3272-041 STEP ASSEMBLY (LH. SHOWN)
D3272-042 STEP ASSEMBLY (RH, OPPOSITE)



DETAIL B
SCALE 1:5

CONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE


WORK ORDER
NO. 53378



DESIGN <i>GP</i>	DRAWN BY <i>JB</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>CE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE 1:20

RELEASED


07.06.04 *[Signature]*



DETAIL C

B D3272-1 STEP

(MAKE FROM D2622-120 STEP EXTRUSION)



DETAIL C
(SCALE 1:5)

DRILL $\phi 0.128$ (#30) FROM JIG ON
BOTH SIDES OF D3272-1 EXTRUSION
TO MATCH D3065-041 HOLE PATTERN

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. **33378**

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.